


**Tilcon New Jersey
 Pompton Lakes Quarry
 Quarterly Blast Data Summary
 3rd Quarter 2016**

Date	Time	Recording Location	Within NJ Ground Vibration Limits*	Within NJ Air Overpressure Limits**
9/6/2016	10:59	211 Hamburg Turnpike	Yes	Yes
9/6/2016	10:59	Cablevision Tower	Yes	Yes
9/13/2016	11:34	211 Hamburg Turnpike	Yes	Yes
9/13/2016	11:34	Cablevision Tower	Yes	Yes
9/15/2016	10:59	211 Hamburg Turnpike	Yes	Yes
9/15/2016	10:59	Cablevision Tower	Yes	Yes
9/19/2016	11:14	211 Hamburg Turnpike	Yes	Yes
9/19/2016	11:14	Cablevision Tower	Yes	Yes
9/26/2016	13:05	211 Hamburg Turnpike	Yes	Yes
9/26/2016	13:05	Cablevision Tower	Yes	Yes
9/26/2016	13:05	Bloomington DPW Yard	Yes	Yes


*State of New Jersey Administrative Code Title 12:190; Subchapter 7.26
 **State of New Jersey Administrative Code Title 12:190; Subchapter 7.25

Comparison of Measured Blast Vibrations to Current U.S. Bureau of Mines Recommendations Tilcon New Jersey Pompton Lakes Quarry 3rd Quarter 2016



*As per State of New Jersey Administrative Code Title 12:190; Subchapter 7.26

Air Overpressure Levels from Tilcon New Jersey - Pompton Lakes Quarry 3rd Quarter 2016



*As per State of New Jersey Administrative Code Title 12.190; Subchapter 7.25

