


**Tilcon New Jersey
Pompton Lakes Quarry
Quarterly Blast Compliance Summary
1st Quarter 2019**

Date	Time	Recording Location	Within NJ Ground Vibration Limits*	Within NJ Air Overpressure Limits**
1/9/2019	11:00	211 Hamburg Turnpike	Yes	Yes
1/9/2019	11:00	Cablevision Tower	Yes	Yes
1/9/2019	11:00	Bloomington DPW Yard	Yes	Yes
2/6/2019	12:30	211 Hamburg Turnpike	Yes	Yes
2/6/2019	12:30	Cablevision Tower	Yes	Yes
2/6/2019	12:30	Bloomington DPW Yard	Yes	Yes
3/1/2019	13:00	211 Hamburg Turnpike	Yes	Yes
3/1/2019	13:00	Cablevision Tower	Yes	Yes
3/1/2019	13:00	Bloomington DPW Yard	Yes	Yes
3/12/2019	11:30	211 Hamburg Turnpike	Yes	Yes
3/12/2019	11:30	Cablevision Tower	Yes	Yes
3/12/2019	11:30	Bloomington DPW Yard	Yes	Yes
3/21/2019	12:15	211 Hamburg Turnpike	Yes	Yes
3/21/2019	12:15	Cablevision Tower	Yes	Yes
3/21/2019	12:15	Bloomington DPW Yard	Yes	Yes
3/26/2019	11:00	211 Hamburg Turnpike	Yes	Yes
3/26/2019	11:00	Cablevision Tower	Yes	Yes
3/26/2019	11:00	Bloomington DPW Yard	Yes	Yes


*State of New Jersey Administrative Code Title 12:190; Subchapter 7.26
**State of New Jersey Administrative Code Title 12:190; Subchapter 7.25

Comparison of Measured Blast Vibrations to Current U.S. Bureau of Mines Recommendations Tilcon New Jersey Pompton Lakes Quarry 1st Quarter 2019



As per State of New Jersey Administrative Code Title 12:190; Subchapter 7.26

Air Overpressure Levels from Tilcon New Jersey - Pompton Lakes Quarry 1st Quarter 2019



*As per State of New Jersey Administrative Code Title 12.190; Subchapter 7.25

211 Hamburg Turnpike
 Cablevision Tower
 Bloomingdale DPW Yard